

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/16/2024

Submitted Date:

05/16/2024

Document Number:

713300911

**FIELD INSPECTION FORM**Loc ID 318295 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Silver, Randy	720-827-6688	randy.silver@state.co.us	
, KPK	303-825-4822	cogcc@kpk.com	all inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241052	WELL	PR	03/20/1995	GW	123-08840	ROCKY MOUNTAIN FUEL B 3	PR

**General Comment:**

Follow up inspection, doc 713300074

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>		
Type	UNUSED EQUIPMENT	
Comment:	disassembled pumping unit	
Corrective Action:	comply with Rule 606	Date: 10/05/2023

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	piped to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric servcie		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	disassemble pumping unit		
Corrective Action:		Date:	

<b>Venting:</b>		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

<b>Flaring:</b>		
Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 241052 Type: WELL API Number: 123-08840 Status: PR Insp. Status: PR**Producing Well**Comment: PR, Valves appeared to be closed at time of inspection

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 02/02/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
ECMC Inspection Report Summary Inspector Michael Kester, conducted an Follow up on-site inspection doc 713300074 Location: Rocky Mountain Fuels B 3 Operator: KPK API#: 123-08840 County: Weld  Unused equipment, Rule 606, Corrective action date 10-5-2023 See photo 1, & 2  Weather conditions: dry and sunny  This is a summary of inspection report. This inspection does not nullify any orders or NOAV from the COGCC	kesterm	05/16/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300912	site pic	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6551248">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6551248</a>