

Interim Reclamation and Stormwater Inspection

April 15, 2024

Operator: FULCRUM ENERGY OPERATING LLC- #10805

Location ID: 436801

Inspection Document #: 697505279

Jackson County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Surprise Unit/2-08H
Location ID: 436801



Photo 1. 2023 NAIP illustrates the location that has been interim reclaimed.

Inspection Photos
Location Name: Surprise Unit/2-08H
Location ID: 436801



Photo 2. Photo taken from the entrance of location. Photo illustrates the Location Operator sign.



Photo 3. Photo taken from the wellhead, facing West. Photo illustrates the well signage that lacks API information.



Inspection Photos
Location Name: Surprise Unit/2-08H
Location ID: 436801



Photo 4. Photo taken from the location, facing East. Photo illustrates the silt fence BMP is in disrepair and has not been properly installed.



Photo 5. Close up photo taken of the improperly installed silt fence BMP.

Inspection Photos
Location Name: Surprise Unit/2-08H
Location ID: 436801



Photo 6. Photo taken from the eastern interim reclamation area, facing Southeast. Photo illustrates disturbances that appear to be related to a remediation project.



Photo 7. Photo taken from the eastern interim reclamation area, facing South. See comments under Photo 6.

Inspection Photos
Location Name: Surprise Unit/2-08H
Location ID: 436801



Photo 8. Photo taken from the eastern interim reclamation area, facing East. Photo illustrates the topsoil stockpile which is not properly stabilized with evidence of erosion without a perimeter BMP.



Photo 9. Photo taken from the topsoil stockpile, facing North. Photo illustrates the topsoil stockpile has not been properly stabilized for long-term stabilization.

Inspection Photos
Location Name: Surprise Unit/2-08H
Location ID: 436801



Photo 10. ECMC GIS aerial imagery illustrates the location falls within Greater Sage Grouse Priority Habitat Management Area.