

Interim Reclamation and Stormwater Inspection

April 15, 2024

Operator: FULCRUM ENERGY OPERATING LLC- #10805

Location ID: 449274

Inspection Document #: 697505287

Jackson County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 1. Drone imagery illustrates a portion of the interim reclamation area needs to be reclaimed. Refer to Photo 4.




Photo 2. Drone imagery illustrates ponding of snowmelt. It appears the working pad surface could be better contoured to allow for better drainage to the outlet. Note- Operator needs to be aware of E&P waste discharging off location via the outlet while draining ponding snowmelt.

Inspection Photos
Location Name: Rabbit Ears 0681 23
Location ID: 449274



Photo 3. Photo taken from the entrance of location. Photo illustrates the Location Operator sign and debris caught in the fencing. This appears to have been removed based on the most recent inspection conducted on May 1, 2024.



Photo 4. Photo taken from the eastern interim reclamation area, facing North. Photo illustrates an area that needs to be reclaimed.

Inspection Photos
Location Name: Rabbit Ears 0681 23
Location ID: 449274



Photo 5. Photo taken from the eastern interim reclamation area, facing North. Photo illustrates interim reclamation has been performed with the evidence of germination of grass species and straw crimped mulch.

Inspection Photos
Location Name: Rabbit Ears 0681 23
Location ID: 449274



Photo 6. ECMC GIS aerial imagery illustrates the location falls within Greater Sage Grouse General Habitat Management Area.