



FORM  
INSP  
  
Rev  
X/20

State of Colorado  
Oil and Gas Conservation Commission  
1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
05/15/2024  
Submitted Date:  
05/15/2024  
Document Number:  
699505813

Loc ID  
444338

Inspector Name:  
MEDINA, JUSTIN

On-Site Inspection ☐  
2A Doc Num: \_\_\_\_\_

**Operator Information:**  
ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Status Summary:**  
☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED  
**Findings:**  
6 Number of Comments  
0 Number of Corrective Actions  
☐ Corrective Action Response Requested  
**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444335	WELL	PR	04/01/2020	OW	123-42562	PUMA FED 30N-14HZ	PR
444336	WELL	PR	09/01/2018	OW	123-42563	PUMA FED 4N-14HZ	PR
444337	WELL	SI	02/01/2024	OW	123-42564	PUMA FED 29C-14HZ	SI
444339	WELL	PR	08/01/2018	OW	123-42565	PUMA FED 5S-35HZ	PR
444340	WELL	PR	09/05/2017	OW	123-42566	PUMA FED 13C-35HZ	PR
444341	WELL	PR	09/06/2017	OW	123-42567	PUMA FED 34N-35HZ	PR
444343	WELL	PR	12/01/2020	OW	123-42568	PUMA FED 4C-14HZ	PR
444344	WELL	PR	09/05/2017	OW	123-42569	PUMA FED 13N-35HZ	PR
444345	WELL	PR	02/01/2017	OW	123-42570	PUMA FED 34C-35HZ	PR

**General Comment:**

Date Run: 5/19/2024 Doc [#699505813]

Page 1 of 3

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: red AG fencing

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Bradenhead

# 9

Comment:

Corrective Action:

Date:

Type: Pump Jack

# 2

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 7

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 2

Comment: electric motor

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: Electrict / automation

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 444335	Type: WELL	API Number: 123-42562	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444336	Type: WELL	API Number: 123-42563	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444337	Type: WELL	API Number: 123-42564	Status: SI	Insp. Status: SI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444339	Type: WELL	API Number: 123-42565	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444340	Type: WELL	API Number: 123-42566	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444341	Type: WELL	API Number: 123-42567	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444343	Type: WELL	API Number: 123-42568	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444344	Type: WELL	API Number: 123-42569	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444345	Type: WELL	API Number: 123-42570	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were clear, calm, warm.	medinaj	05/15/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505814	inspection pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6553322">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6553322</a>