



FORM  
INSP  
  
Rev  
X/20

State of Colorado  
Oil and Gas Conservation Commission  
1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
05/15/2024  
Submitted Date:  
05/15/2024  
Document Number:  
699505815

Loc ID  
444427

Inspector Name:  
MEDINA, JUSTIN

On-Site Inspection ☐  
2A Doc Num: \_\_\_\_\_

**Operator Information:**  
ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Status Summary:**  
☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED  
**Findings:**  
6 Number of Comments  
0 Number of Corrective Actions  
☐ Corrective Action Response Requested  
**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444424	WELL	PR	08/01/2023	OW	123-42622	JAGUAR 14N-35HZX	PR
444425	WELL	PR	08/01/2023	OW	123-42623	JAGUAR FED 35N-35HZ	PR
444426	WELL	PA	10/13/2017	LO	123-42624	JAGUAR 36C-35HZ	PA
444428	WELL	PR	07/01/2023	OW	123-42625	JAGUAR 3N-14HZ	PR
444429	WELL	PR	07/01/2023	OW	123-42626	JAGUAR 3C-14HZ	PR
444430	WELL	PR	07/01/2023	OW	123-42627	JAGUAR FED 29N-14HZ	PR
444431	WELL	PR	07/01/2023	OW	123-42628	JAGUAR 28C-14HZ	PR
444432	WELL	PR	08/01/2023	OW	123-42629	JAGUAR FED 35C-35HZ	PR
444433	WELL	PR	06/13/2017	OW	123-42630	JAGUAR FED 6S-35HZ	PR
448519	SPILL OR RELEASE	CL	11/28/2016		-	SPILL/RELEASE POINT	CL

**General Comment:**

Date Run: 5/19/2024 Doc [#699505815]

Page 1 of 4

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Plunger Lift

# 7

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 1

Comment: electric motor

Corrective Action:

Date:

Type: Pump Jack

# 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: electric / automation

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 444424	Type: WELL	API Number: 123-42622	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444425	Type: WELL	API Number: 123-42623	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444426	Type: WELL	API Number: 123-42624	Status: PA	Insp. Status: PA
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444428	Type: WELL	API Number: 123-42625	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444429	Type: WELL	API Number: 123-42626	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444430	Type: WELL	API Number: 123-42627	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444431	Type: WELL	API Number: 123-42628	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444432	Type: WELL	API Number: 123-42629	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444433	Type: WELL	API Number: 123-42630	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 448519	Type: SPILL OR	API Number: -	Status: CL	Insp. Status: CL
---------------------	----------------	---------------	------------	------------------

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: Fluid Type:

End Surf Csg Pressure:

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were clear, calm, warm.	medinaj	05/15/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505816	inspection pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6553323">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6553323</a>