

Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN ASTRAL FED FEE 1-26-6S-94W Pad

Location ID: 311532



Photo # 7490 From entrance to location



Photo # 7491 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN ASTRAL FED FEE 1-26-6S-94W Pad

Location ID: 311532



Photo # 7492 Location



Photo # 7493 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN ASTRAL FED FEE 1-26-6S-94W Pad

Location ID: 311532



Photo # 7494 Location



Photo # 7495 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN ASTRAL FED FEE 1-26-6S-94W Pad

Location ID: 311532



Photo # 7496 Open ended load line




Photo # 7497 Production tank missing required information

Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN ASTRAL FED FEE 1-26-6S-94W Pad

Location ID: 311532



Photo # 7498 Wellhead sign not properly posted



Photo # 7499 Dead weeds/debris

Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN ASTRAL FED FEE 1-26-6S-94W Pad

Location ID: 311532



Photo # 7500 Wire fencing around tank battery needs maintenance



Photo # 7501 Wire fencing around tank battery needs maintenance