

Interim Reclamation and Stormwater Inspection

Date: 5/7/24

Operator: Kerr McGee Oil & Gas Onshore LP - 47120

Location ID: 416717

Inspection Document #: 713900619

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: SCHLAGEL 10-5HZ PAD
Location ID: 416717



Photo 1. The photo was taken at the entrance to the well location facing Northeast. The photo illustrates the Operator location sign.



Photo 2. The photo was taken at the well location facing West. The photo illustrates the North side of the production pad and fencing around production equipment.

Inspection Photos
Location Name: SCHLAGEL 10-5HZ PAD
Location ID: 416717



Photo 3. The photo was taken at the well location facing Northeast. The photo illustrates the access road.




Photo 4. The photo was taken at the well location facing Southwest. The photo illustrates the South side of the production pad.

Note - Operator representative on location mentioned temporary tanks are to be removed in the near future.

Inspection Photos
Location Name: SCHLAGEL 10-5HZ PAD
Location ID: 416717



Photo 5. The photo was taken from the well location facing North. The photo illustrates rill erosion on the Southeast side of the production facility.



Photo 6. The photo was taken at the well location facing North. The photo illustrates stained soil around the wellheads.

Inspection Photos
Location Name: SCHLAGEL 10-5HZ PAD
Location ID: 416717



Photo 7. The photo was taken from the well location facing Northeast. The photo illustrates the perimeter ditch and berm around the wellhead pad.

Photo 8. The photo was taken at the well location facing Southeast. The photo illustrates a rip-rap protected outflow.

Inspection Photos
Location Name: SCHLAGEL 10-5HZ PAD
Location ID: 416717



Photo 9. The photo was taken from the well location facing Southwest. The photo illustrates the apparent unprotected topsoil stockpile and equipment being stored on the wellhead pad.

Photo 10. The photo was taken at the well location facing Northeast. The photo illustrates the unprotected topsoil stockpile.

Inspection Photos
Location Name: SCHLAGEL 10-5HZ PAD
Location ID: 416717



Photo 11. The photo was taken at the well location facing Southwest. The photo illustrates some erosion along the base of the unprotected stockpile and equipment being stored on the wellhead pad.