

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/13/2024

Submitted Date:

05/20/2024

Document Number:

708302171

**FIELD INSPECTION FORM**Loc ID 324485 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Energy, Gunnison		geops@oxbow.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283917	WELL	SI	09/01/2022	GW	051-06075	HOTCHKISS FEDERAL 12-89 18-43	SI
436617	WELL	PR	02/01/2022	CBM	051-06126	DGU Federal 1289 18-43 CS2	PR

**General Comment:****COGCC Inspection Report Summary**

On 5/13/2024 at approximately 12:45, Compliance Inspector Matthew Morris conducted a follow-up inspection at GUNNISON ENERGY LLC, DGU Federal 1289/18-43 Pad at Location ID #324485 in Gunnison County, Colorado.

During the inspection, the following compliance issues were observed:

- 1) Stored supplies across location
- 2) Debris across location
- 3) Multiple open-ended lines in tank battery (Heaters and knock out)
- 4) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911/(970) 874-7697

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Stored supplies present across location.		
Corrective Action:	Remove stored supplies to comply with Rule 606.	Date:	05/27/2024
Type	DEBRIS		
Comment:	Debris present across location.		
Corrective Action:	Remove debris to comply with Rule 606.	Date:	05/27/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Livestock corrals		
Corrective Action:		Date:	
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Vertical Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 3	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 2	
Comment:		
Corrective Action:		Date:
Type: Vertical Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Pig Station	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 5	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	500 BBLS	HEATED STEEL AST		,
Comment:	Multiple open-ended lines on tanks pose wildlife entry hazards.				
Corrective Action:	Secure open-ended lines to comply with Rule 608.e.				Date: 05/25/2024

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Other	Fail			Insufficient erosion control
Seeding						
		Gravel				
Gravel						
Drains						
		Sediment Traps				
Rip Rap						
Ditches						
Berms						
Sediment Traps						
Compaction						
		Compaction				
		Seeding				
		Culverts				
		Check Dams	Fail			BMP needs maintenance

Comment: Check dams on lease road to location are full of sediment and need maintained. No erosion controls on cut slope above check dams and ditch.

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 06/04/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	284075	1433361	
	284075	1433361	

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708302173	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6555374">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6555374</a>