

Caerus Piceance LLC
Piceance Creek Unit T32X-33G
Location ID: 316301



As signs are replaced additional information is required.
Needs turned facing entrance.



As signs are replaced additional information is required

Caerus Piceance LLC
Piceance Creek Unit T32X-33G
Location ID: 316301



Lack of Stormwater BMP maintenance.



Lack of Stormwater BMP maintenance.

Caerus Piceance LLC
Piceance Creek Unit T32X-33G
Location ID: 316301



Erosion and sediment migration



Erosion and sediment migration

Caerus Piceance LLC
Piceance Creek Unit T32X-33G
Location ID: 316301



Stormwater BMPs need maintenance



Stormwater BMPs need maintenance

Caerus Piceance LLC
Piceance Creek Unit T32X-33G
Location ID: 316301



Debris



Rathole cover

Caerus Piceance LLC
Piceance Creek Unit T32X-33G
Location ID: 316301



Tank battery sign not displayed



Tank battery from Southeast corner

Caerus Piceance LLC
Piceance Creek Unit T32X-33G
Location ID: 316301



Location from Southeast corner



Location from Southwest corner

Caerus Piceance LLC
Piceance Creek Unit T32X-33G
Location ID: 316301



Location from Northwest corner



Location from Northeast corner