



ECMC Field Inspection Report Response (FIRR) Photographic Log

Fluharty Tank Battery

Field Inspection Form #: 711900661

(May 8, 2024)



Description:
West Padroni Tank
Battery with
fiberglass insulated
tank removed

Date: 5/8/24



Description:
Fluharty Tank
Battery equipment
tank removed
looking NE from the
West Padroni Tank
Battery access road

Date: 5/8/24

Note: Flowline
risers still present in
photo, but lines
shall be removed or
abandoned per the
ECMC
requirements.



Description:
Fluharty Tank
Battery equipment
tank removed
looking E from the
West Padroni Tank
Battery access
road.

Date: 5/8/24

Note: Flowline
risers still present in
photo, but lines
shall be removed or
abandoned per the
ECMC
requirements.



Description:
Fluharty Tank
Battery equipment
tank removed
looking N.

Date: 5/8/24

Note: Flowline
risers still present in
photo, but lines
shall be removed or
abandoned per the
ECMC
requirements.