

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
05/06/2024
Submitted Date:
05/16/2024
Document Number:
699700374

FIELD INSPECTION FORM

Loc ID 322372 Inspector Name: Heil, John On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
3 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 51130
 Name of Operator: LOCIN OIL CORPORATION
 Address: 600 TRAVIS ST STE 6161
 City: HOUSTON State: TX Zip: 77002

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Arnim, Rees	(713) 469-0275	rarnim@locin.energy	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
119474	PIT	AC			-	Federal #22-9 119474	EI
119475	PIT	AC			-	Federal #22-9 119475	EI
210380	WELL	SI	06/01/2020	GW	045-06136	FEDERAL 22-9	EI

General Comment:
[ECMC Environmental Inspection.](#)

Inspected Facilities

Facility ID: 119474 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 119475 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 210380 Type: WELL API Number: 045-06136 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: NO Pit ID: 119474 Lat: 39.383971 Long: -108.996262

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Other Liner Condition: _____

Comment: Undisierable vegetation within the pit.

Corrective Action Operator shall comply with 909.b and remove the undesirable vegetation.
Operator shall comply with Rule 909.j Produced Water Quality Analyses.

Date: 06/17/2024

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: Mesh Netting Condition: Good

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

Type: Evaporation Lined: NO Pit ID: 119475 Lat: 39.384110 Long: -108.996609

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Other Liner Condition: _____

Comment: Undisierable vegetation within the pit.

Corrective Action Operator shall comply with 909.b and remove the undesirable vegetation.
Operator shall comply with Rule 909.j Produced Water Quality Analyses.

Date: 06/17/2024

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: Mesh Netting Condition: Good

Comment:		Date:
Corrective Action		
Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:		
Comment:		Date:
Corrective Action		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403794105	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6550864
699700375	20240506 federal 22-9	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6550857