

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/16/2024

Submitted Date:

05/16/2024

Document Number:

713300909

FIELD INSPECTION FORMLoc ID 317649 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	all inspections
Silver, Randy	720-827-6688	randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239689	WELL	PR	03/20/1995	GW	123-07477	ROCKY MOUNTAIN FUEL CO B 1	PR

General Comment:

Follow up inspection, doc 713300072

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	dissassembled pumping unit		
Corrective Action:	comply with Rule 606	Date:	10/02/2023

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	electric service, metal panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	pipd to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	dissassembled on edge of well site		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electrical service		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:		
Type		

Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 239689 Type: WELL API Number: 123-07477 Status: PR Insp. Status: PR

Producing Well

Comment: PR Valves appeared to be closed at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/03/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
ECMC Inspection Report Summary Inspector Michael Kester, conducted an Follow up on-site inspection. Location: Rocky Mountain Fuel Co B 1 Operator: KPK API#: 123-07477 County: Weld During this inspection the following possible compliance issues were observed: Unused equipment, Rule 606, corrective action date 10-2-2023 see attached photos 1, 2, 3 & 4 Weather conditions: Dry and sunny This is a summary of inspection report. This inspection does not nullify any orders or NOAV from the COGCC	kesterm	05/16/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403794406	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6551251
713300910	site pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6551247