

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/16/2024

Submitted Date:

05/16/2024

Document Number:

713300915

FIELD INSPECTION FORM

Loc ID 410187 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	all inspections
Silver, Randy	720-827-6688	randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241083	WELL	PR	03/20/1995	GW	123-08871	ROCKY MOUNTAIN FUEL CO C 7	PR

General Comment:

[Follow up inspection, doc 71300078](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	concrete pad for pumping unit		
Corrective Action:	comply with Rule 606	Date:	10/05/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	electric panel		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Ancillary equipment	# 1		
Comment:	electric panel		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	piped to surface		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
------	--	--	--

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 241083 Type: WELL API Number: 123-08871 Status: PR Insp. Status: PR

Producing Well

Comment: PR. Valves appeared to be closed at time of inspection

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 02/02/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary Inspector Michael Kester, conducted an Follow up on-site inspection doc 713300078 Location: Rocky Mountain Fuels CO C 7 Operator: KPK API#: 123-08871 County: Weld</p> <p>Unused equipment, Rule 606, Corrective action date 10-5-2023 See photo 1, & 2</p> <p>Weather conditions: dry and sunny</p> <p>This is a summary of inspection report. This inspection does not nullify any orders or NOAV from the COGCC</p>	kesterm	05/16/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403794409	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6551254
713300916	site pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6551250