

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/21/2024

Submitted Date:

05/21/2024

Document Number:

714201045**FIELD INSPECTION FORM**Loc ID 332306 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271733	WELL	SI	01/01/2024	OW	123-22118	BROWN 2-6	TA
422506	WELL	SI	07/01/2021	GW	123-33288	LEE 21-6	TA
422515	WELL	SI	07/01/2021	OW	123-33293	LEE 7-6	TA
422518	WELL	SI	07/01/2021	OW	123-33296	LEE 28-6	TA

General Comment:[THIS IS A FOLLOW UP INSPECTION.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	debris on various areas of location. see attached photos.		
Corrective Action:	Comply with Rule 606	Date:	06/04/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	wire		
Corrective Action:		Date:	

Equipment:

Type: Other	#		corrective date
Comment:	It appears to be the same amount of equipment stated in previous inspection DOC#: 714200127.		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 271733 Type: WELL API Number: 123-22118 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTEDComment: TA; Form 6A in well file.Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 01/12/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 12 Fluid Type: NoneEnd Surf Csg Pressure: --Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422506 Type: WELL API Number: 123-33288 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTEDComment: TA; Form 6A in well file.Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 01/12/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: NoneEnd Surf Csg Pressure: --Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422515 Type: WELL API Number: 123-33293 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTEDComment: TA; Form 6A in well file.Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 01/12/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NoneEnd Surf Csg Pressure: --Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422518 Type: WELL API Number: 123-33296 Status: SI Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; Form 6A in well file.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/17/2024

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 2

Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input type="text"/>						Date: <input type="text"/>
Corrective Action: <input type="text"/>						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 714200127. IT APPEARS ALL PREVIOUS CORRECTIVE ACTIONS ASSIGNED TO THIS LOCATION HAVE BEEN RESOLVED. ONE NEW CORRECTIVE ACTION WAS OBSERVED AT THE TIME OF RE-INSPECTION. Please review my findings down below for additional information.</p> <p>ECMC Inspection Report Summary WEATHER CONDITIONS: cloudy, dry ground. On Tuesday, May 21, 2024 at approximately 1315, I, Inspector Brittani Santistevan, conducted an on-site inspection at BROWN 2-6, 7, 21, 28-6 (Kerr McGee Oil and Gas Onshore), at location ID: 332306 in WELD COUNTY, Colorado. While there, I observed a shut in facility. During this inspection the following possible compliance issues were observed: 1. It appears to be debris on location. Comply with Rule 606. (Corrective Action Date: June 4, 2024) See attached photo #3-9.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	05/21/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201046	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6559605