

Inspection Photos

May 21st 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 326297

Inspection Document #: 714000781

La Plata County, CO

Township: SWSE 33 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



CO L O R A D O

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Huber Lewis 2-33
Location ID: 326297



Photo 1. View of the well pad taken from the access point facing center.



Inspection Photos
Location Name: Huber Lewis 2-33
Location ID: 326297



Photo 2. View of the western interim reclamation area facing south. Vegetation predominately comprised of western wheatgrass.

Inspection Photos
Location Name: Huber Lewis 2-33
Location ID: 326297



Photo 3. Unused oil and gas piping equipment observed on location.

Inspection Photos
Location Name: Huber Lewis 2-33
Location ID: 326297



Photo 4. View of gully erosion identified in previous inspection doc that has been collapsed, regraded and reseeded. Germination of western wheatgrass observed.

Inspection Photos

Location Name: Huber Lewis 2-33

Location ID: 326297



Photo 5. New storm water divergent channel has not been installed per good engineering practices. Rill erosion and evidence of sediment transport persists, additional stabilization is needed in this area.

Inspection Photos

Location Name: Huber Lewis 2-33

Location ID: 326297



Photo 6. Impacted surface material observed at the pump jack muffler and well head.

Inspection Photos
Location Name: Huber Lewis 2-33
Location ID: 326297



5/21/24
+37.254087,-107.747836
301° NW

Photo 7. Large patch of field bindweed observed in the northeast corner of the disturbance.

Inspection Photos
Location Name: Huber Lewis 2-33
Location ID: 326297

5/21/24
+37.254087,-107.747836
37° NE



Photo 8. View of the reference area predominantly comprised of western wheatgrass and sagebrush.