

# Interim Reclamation and Stormwater Inspection

Date: 5/14/24

Operator: Renegade Oil & Gas Company LLC - 74165

Location ID: 320644

Inspection Document #: 713900627

Arapahoe County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos

Location Name: Lowry State-65S65W 25SWSW

Location ID: 320644



**Photo 1.** The photo was taken at the tank battery location facing South. The photo illustrates erosion has filled and overtopped the rip rap check dam.

**Photo 2.** The photo was taken at the tank battery location facing Southwest. The photo illustrates the erosion along the West side of the tank battery pad.

Inspection Photos

Location Name: Lowry State-65S65W 25SWSW

Location ID: 320644



**Photo 3.** The photo was taken at the tank battery location facing East. The photo illustrates erosion leaving the tank battery location beyond another rip rap check dam.

**Photo 4.** The photo was taken at the tank battery location facing East. The photo illustrates the end of the sedimentation off the tank battery location.

Inspection Photos  
Location Name: Lowry State-65S65W 25SWSW  
Location ID: 320644



**Photo 5.** The photo was taken from onX imagery of the tank battery location. The photo illustrates the mapped boundary of erosion of the location. Sediment was observed approximately 550ft off location.

## Inspection Photos

Location Name: Lowry State-65S65W 25SWSW

Location ID: 320644



**Photo 6.** The photo was taken at the tank battery location facing Northwest. The photo illustrates tank placards are cracking and need replaced.



**Photo 7.** The photo was taken at the tank battery location facing West. The photo illustrates erosion has pushed a hole through the secondary containment berm of the tank batteries.

## Inspection Photos

Location Name: Lowry State-65S65W 25SWSW

Location ID: 320644



**Photo 8.** The photo was taken at the tank battery location facing Southwest. The photo illustrates an open pipe with no cap or other wildlife BMP.

**Photo 9.** The photo was taken at the tank battery location facing Southeast. The photo illustrates bare areas of soil around what appears to be a former pit as well as other oil & gas equipment.

Inspection Photos

Location Name: Lowry State-65S65W 25SWSW

Location ID: 320644



**Photo 10.** The photo was taken at the well location facing Northeast. The photo illustrates erosion off the well location.

**Photo 11.** The photo was taken at the well location facing Southwest. The photo illustrates an example of soil staining that occurs across the well location.

Inspection Photos

Location Name: Lowry State-65S65W 25SWSW

Location ID: 320644



**Photo 12.** The photo was taken at the tank battery location facing Southwest. The photo illustrates the erosion for both the well and tank battery locations begins above the location on the access road and should be treated from top to bottom.