

Interim Reclamation and Stormwater Inspection

Date: 5/14/24

Operator: Renegade Oil & Gas Company LLC - 74165

Location ID: 320648

Inspection Document #: 713900628

Arapahoe County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: State of Colo 'T' NCT-1-65S65W

25NESW

Location ID: 320648



Photo 1. The photo was taken at the well location facing Southeast. The photo illustrates the Operator sign.



Photo 2. The photo was taken at the tank battery location facing East. The photo illustrates erosion created from the secondary containment drain.

Inspection Photos

Location Name: State of Colo 'T' NCT-1-65S65W

25NESW

Location ID: 320648



Photo 3. The photo was taken at the tank battery location facing West. The photo illustrates the unused equipment within the secondary containment of the tank batteries.



Photo 4. The photo was taken at the tank battery location facing South. The photo illustrates stained soil within the tank battery area.

Inspection Photos

Location Name: State of Colo 'T' NCT-1-65S65W

25NESW

Location ID: 320648



Photo 5. The photo was taken at the tank battery location facing North. The photo illustrates standing water within secondary containment of the tank battery.

Photo 6. The photo was taken at the tank battery location facing East. The photo illustrates erosion/sedimentation pooling into the secondary containment drain.

Inspection Photos

Location Name: State of Colo 'T' NCT-1-65S65W

25NESW

Location ID: 320648



Photo 7. The photo was taken at the tank battery location facing Northeast. The photo illustrates uncapped pipes on production equipment.



Photo 8. The photo was taken at the tank battery location facing Southwest. The photo illustrates an area of former disturbance that is still in the process of being restored as well as unused equipment indicated by the red arrow.

Inspection Photos

Location Name: State of Colo 'T' NCT-1-65S65W

25NESW

Location ID: 320648



Photo 9. The photo was taken at the well location facing Northwest. The photo illustrates sediment carried along the access road between the tank battery to wellhead pads.



Photo 10. The photo was taken at the wellhead location facing South. The photo illustrates standing water on the wellhead pad.

Note - Erosion appears to be moving from the tank battery pad down the access road and pooling on the wellhead pad. Sediment and stormwater did not appear to be flowing off location at the time of inspection.

Inspection Number: 713900628



Photo 11. The photo was taken at the well location facing South. The photo illustrates tank placards need replacing and secondary containment is missing wildlife netting.