

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/22/2024

Submitted Date:

05/23/2024

Document Number:

714201047

FIELD INSPECTION FORM

Loc ID 329537 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 18 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249687	WELL	SI	01/01/2024	OW	123-17490	NICHOLS 33-6	TA
422371	WELL	SI	07/01/2020	OW	123-33236	NICHOLS 24-6	TA
422374	WELL	SI	07/01/2020	OW	123-33237	NICHOLS 23-6	TA
422435	WELL	SI	07/01/2020	OW	123-33254	NICHOLS 10-6	TA
422453	WELL	SI	07/01/2020	OW	123-33264	NICHOLS 38-6	TA
422461	WELL	SI	07/01/2020	OW	123-33268	NICHOLS 9-6	TA
422463	WELL	SI	07/01/2020	OW	123-33269	NICHOLS 16-6	TA

General Comment:

[THIS IS A FOLLOW UP INSPECTION.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	debris on various areas of tank battery location. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	06/06/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	wire		
Corrective Action:		Date:	

Equipment:

Type: Other	#		corrective date
Comment:	it appears all equipment remains the same as recorded in previous inspection DOC#: 67960353.		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 249687 Type: WELL API Number: 123-17490 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; Form 6A in well file.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 01/24/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 9 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422371 Type: WELL API Number: 123-33236 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; Form 6A in well file.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 01/16/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422374 Type: WELL API Number: 123-33237 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; Form 6A in well file.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 01/16/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422435 Type: WELL API Number: 123-33254 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; Form 6A in well file.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/16/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: None

End Surf Csg Pressure: --

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422453 Type: WELL API Number: 123-33264 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; Form 6A in well file.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/16/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422461 Type: WELL API Number: 123-33268 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; Form 6A in well file.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/16/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 422463 Type: WELL API Number: 123-33269 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; Form 6A in well file.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/16/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 67960353. IT APPEARS ALL PREVIOUS CORRECTIVE ACTIONS ASSIGNED TO THIS LOCATION HAVE BEEN RESOLVED. ONE NEW CORRECTIVE ACTION WAS OBSERVED AT THE TIME OF RE-INSPECTION. Please review my findings below for additional information.</p> <p>ECMC Inspection Report Summary WEATHER CONDITIONS: sunny, dry ground. On Wednesday, May 22, 2024 at approximately 10:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at NICHOLS 10-6 (Kerr McGee Oil & Gas Onshore), at location ID: 329537 in WELD COUNTY, Colorado. While there, I observed a shut in facility. During this inspection the following possible compliance issues were observed: 1. It appears to be debris on various areas of the tank battery location. Comply with Rule 606. (Corrective Action Date: June 6, 2024) See attached photo #2-7, 9-11, 13, .</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	05/23/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201049	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6560420