

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/17/2024

Submitted Date:

05/17/2024

Document Number:

714201030

**FIELD INSPECTION FORM**

Loc ID 336212 Inspector Name: Santistevan, Brittani On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249902	WELL	TA	04/30/2019	GW	123-17705	UPRC 33-15J5	TA
300675	WELL	SI	05/01/2022	GW	123-29816	CANNON X 04-27D	TA
414500	WELL	SI	05/01/2022	GW	123-30765	CANNON X 04-28D	TA

**General Comment:**

[THIS A FOLLOW UP INSPECTION.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	debris on some areas of location. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	05/31/2024

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Other	#		corrective date
Comment:	It appears all equipment remains to be the same as documented in previous DOC#: 714200245.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 249902 Type: WELL API Number: 123-17705 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA: Form 6A in well file.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 02/21/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 300675 Type: WELL API Number: 123-29816 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; form 6A in well file.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 02/01/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 12 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 414500 Type: WELL API Number: 123-30765 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA; Form 6A in well file.

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 02/01/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><b>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 714200245. All previous corrective actions assigned to this location appear to have been resolved. One new corrective action was observed at the time of re-inspection. Review form below for additional information.</b></p> <p>ECMC Inspection Report Summary  <b>WEATHER CONDITIONS:</b> sunny, dry ground                      On Friday, May 17, 2024 at approximately 1145, I, Inspector Brittani Santistevan, conducted an on-site inspection at CANNON X 04-27D, (Kerr McGee Oil &amp; Gas Onshore), at location ID: 336212 in WELD COUNTY, Colorado.                      While there, I observed a shut-in facility.                      During this inspection the following possible compliance issues were observed:                      1. It appears to be debris/weeds on various areas of location. Comply with Rule 606. (Corrective Action Date: May 31, 2024) See attached photo #5, 7.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	santistb	05/17/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403795313	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6552209">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6552209</a>
714201031	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6552205">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6552205</a>