

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/17/2024

Submitted Date:

05/17/2024

Document Number:

714201032

FIELD INSPECTION FORMLoc ID 331224 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427885	WELL	PR	06/01/2018	OW	123-35153	WEICHEL 27N-11HZ	PR
427894	WELL	PR	11/01/2018	OW	123-35161	WEICHEL 2N-11HZ	PR
427900	WELL	PR	06/01/2018	OW	123-35165	WEICHEL 27C-11HZ	PR

General Comment:

THIS IS A FOLLOW UP INSPECTION.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	WEEDS		
Comment:	overgrown vegetation surrounding wellheads. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	05/31/2024

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	It appears fencing is damaged. See attached photos.		
Corrective Action:	Comply with Rule 603.h.	Date:	05/31/2024

Equipment:			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	427885	Type:	WELL	API Number:	123-35153	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Pr; Valves appears to be in an open position.								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	427894	Type:	WELL	API Number:	123-35161	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR; Valves appears to be in an open position.								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	427900	Type:	WELL	API Number:	123-35165	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR; Valves appears to be in an open position.								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 714200323. All previous corrective actions assigned to this location appear to have been resolved. Two new corrective actions were observed at the time of re-inspection. Review form below for additional information.</p> <p>ECMC Inspection Report Summary WEATHER CONDITIONS: sunny, dry ground On Friday, May 17, 2024 at approximately 1130, I, Inspector Brittani Santistevan, conducted an on-site inspection at WEICHEL 2N-11HZ, (Kerr McGee Oil & Gas Onshore), at location ID: 331224 in WELD COUNTY, Colorado. While there, I observed a producing facility. During this inspection the following possible compliance issues were observed: 1. It appears to be debris/weeds on various areas of location. Comply with Rule 606. (Corrective Action Date: May 31, 2024) See attached photo #1-9. 2. It appears some of the fencing is damaged. Comply with Rule 603.h. (Corrective Action Date: May 31, 2024) See attached photo #5.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	05/17/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403795315	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6552210
714201033	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6552206