

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Wasatch Compressor Station

Facility # 467146



Photo # 8051 From entrance to location



Photo # 8052 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Wasatch Compressor Station

Facility # 467146




Photo # 8053 Location



Photo # 8054 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Wasatch Compressor Station

Facility # 467146



Photo # 8055 Location



Photo # 8056 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Wasatch Compressor Station

Facility # 467146



Photo # 8057 Location



Photo # 8058 Staining near compressor

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Wasatch Compressor Station

Facility # 467146



Photo # 8059 PRV vent line lacks cap/does not comply with CECMC pressure safety device rules



Photo # 8060 PRV vent line lacks cap/does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Wasatch Compressor Station

Facility # 467146



Photo # 8061 Stack/piping lacks wildlife protection/does not comply with CECMC wildlife rules



Photo # 8062 Stack/piping lacks wildlife protection/does not comply with CECMC wildlife rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Wasatch Compressor Station

Facility # 467146



Photo # 8063 PRV vent line lacks cap/does not comply with CECMC pressure safety device rules



Photo # 8064 PRV vent line lacks cap/does not comply with CECMC pressure safety device rules