

Final Reclamation Inspection

May 22, 2024

Operator: NEWPEK LLC #10484

Location ID: 445039

Inspection Document #: 697505306

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Fauver #1-20
Location ID: 445039



Photo 1. Photo taken from the well location entrance off CR 102, facing East. Photo illustrates the Operator well sign.



Photo 2. Photo taken from the northern section of the well location access road, facing South. Photo illustrates the establishment of grass species but it is not uniform or reflective of reference area vegetative levels. The access road has a high density of cheatgrass and annual vegetation. There is evidence of mowing with remnant annual stocks.



Inspection Photos
Location Name: Fauver #1-20
Location ID: 445039



Photo 3. Photo taken just west of the location along the west-east access road section, facing West. Photo illustrates the establishment of grass species but it is not uniform or reflective of reference area vegetative levels.



Photo 4. Photo taken from the southern location, facing East. See comments under Photo 2 and 3.



Inspection Photos
Location Name: Fauver #1-20
Location ID: 445039



Photo 5. Photo taken from the eastern location, facing North. Photo illustrates a section that is dominated by annual, weedy Kochia vegetation.



Photo 6. Photo taken from the northern location, facing East. See comments under Photo 2 and 3.



Inspection Photos
Location Name: Fauver #1-20
Location ID: 445039



Photo 7. Photo taken from the western location, facing North. Photo illustrates the reference area vegetation in comparison to the location.



Inspection Photos
Location Name: Fauver #1-20
Location ID: 445039



Photo 8. Photo taken from the location. Photo illustrates Orchardgrass, which is an introduced grass species that is not reflective of reference area vegetation.



Photo 9. Photo taken from the location. Photo illustrates Smooth brome grass, which is an introduced grass species that is not reflective of reference area vegetation.

Inspection Photos
Location Name: Fauver #1-20
Location ID: 445039



Photo 10. Photo taken from the location. Photo illustrates Siberian wheatgrass, which is an introduced grass species that is not reflective of reference area vegetation.

