

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/24/2024

Submitted Date:

05/28/2024

Document Number:

707602858

## FIELD INSPECTION FORM

Loc ID 302196 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

## Operator Information:

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

## Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

## Findings:

9 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response RequestedANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE

## Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

## Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287001	WELL	PA	03/02/2022	OW	123-27338	LOUSTALET B 15-15X	PA

## General Comment:

This is a PLUGGED & ABANDONED WELL inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Battery: Abandoned. MOST equipment has been removed.  
Abandoned Battery SE corner GPS coordinates: 40.396017 / -104.532405

Abandoned Centralized Battery formerly served 5 Location IDs  
(410190, 302196, 327675, 327679, 331929).  
(Well(s): 6: Plugged & Abandoned | PA).

Location					
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment:					Date: _____
Corrective Action:					
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:					
Type: Horizontal Heated Separator		# 0		corrective date	
Comment:		Plugged & Abandoned   PA. Battery Abandoned. Equipment removed.			
Corrective Action:					Date:
Type: Plunger Lift		# 0			
Comment:		Plugged & Abandoned   PA. Equipment removed.			
Corrective Action:					Date:
Type: Gas Meter Run		# 0			
Comment:		Plugged & Abandoned   PA. Battery Abandoned. Equipment removed.			
Corrective Action:					Date:
Type: Emission Control Device		# 0			
Comment:		Plugged & Abandoned   PA. Battery Abandoned. Equipment removed.			
Corrective Action:					Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:		Plugged & Abandoned   PA. Battery Abandoned. Equipment removed.			
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	

Comment:								
Corrective Action:							Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS			
CRUDE OIL	0				,			
Comment:		Plugged & Abandoned   PA. Battery Abandoned. Equipment removed.						
Corrective Action:							Date:	
<u>Paint</u>								
Condition								
Other (Content)								
Other (Capacity)								
Other (Type)								
<u>Berms</u>								
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance				
Comment:								
Corrective Action:							Date:	
<u>Venting:</u>								
Yes/No								
Comment:								
Corrective Action:						Date:		
<u>Flaring:</u>								
Type								
Comment:								
Corrective Action:						Date:		

**Inspected Facilities**

Facility ID: 287001 Type: WELL API Number: 123-27338 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Synopsis:</b></p> <p>On FRI 05/24/2024 at approximately 15:51 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: LOUSTALET B-65N64W/15SWSE Location ID: 302196 Well Name(s) &amp; API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged &amp; Abandoned   PA. Battery: Abandoned. MOST equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.396017 / -104.532405</p> <p><b>WELL STATUS COMMENT:</b> Plugged &amp; Abandoned   PA. Form 6-SRA on file. Plugging, cut/cap date: 03/02/2022. Approved. Plugged &amp; Abandoned   PA well GPS coordinates: 40.393418 / -104.532963</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	05/28/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602859	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6565469">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6565469</a>