

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/29/2024

Submitted Date:

05/29/2024

Document Number:

716400148

**FIELD INSPECTION FORM**

Loc ID 318207 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 14 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
,		rwatzman@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240872	WELL	PR	04/27/1976	OW	123-08660	DITLEV-SIMONSEN C 1	PR

**General Comment:**

[This is a wellsite inspection.](#)

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well information is faded, not legible.		
Corrective Action:	Install sign to comply with Rule 605.g.		Date: 06/29/2024
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Excavation stock pile/debris has a sign that states it is contaminated sits to the east of the wellsite set on plastic liner that is starting to disintegrate.		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.(2)C		Date: 05/31/2024
Type			
Comment:			
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Chainlink topped with barb wire		
Corrective Action:			Date:
Type	OTHER		
Comment:	The open pipeline excavation has Temp. orange construction fence in need of attention.		
Corrective Action:	Comply with 913.b(5).B Operators will fence or cover open excavations to prevent access when sites are not attended.		Date: 02/05/2024
Type	OTHER		
Comment:	Ancillary equip. has fabricated steel pipe and round stock.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Shares fence with the WH, Angle iron.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Prime Mover			corrective date
		# 1	

Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel, Meter box and transformers.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 240872 Type: WELL API Number: 123-08660 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 09/11/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      On Wednesday 5-29-2024 at approximately 1230 hrs. I, Inspector Robbie Revas,                      Conducted an on-site inspection:                      Operator: KP Kauffman                      Location name:                      Location ID # 318207                      Well Name: Ditlev-Simonsen C1                      API # 05-123-08660                      County: Weld                      Weather: Overcast/windy                      Location: dry                      While there, I observed a wellsite, SI at the time of the inspection.                      During this inspection, I observed the following possible compliance issues:                      605.g Signs Gen. Cond: CA date 6-29-2024                      913.B.i: CA date 2-5-2024                      1002.f.(2)C: CA date 5-31-2024                      See attached photos.                      A follow up site inspection is needed to ensure that the addressed                      Compliance issues comply with ECMC rules.                      Any Corrective Actions from previous inspections not addressed are still applicable.</p>	revasr	05/29/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716400150	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6566961">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6566961</a>