

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER A10 well

Location ID: 311651

API # 045-12398



Photo # 8467 From entrance to location



Photo # 8468 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER A10 well

Location ID: 311651

API # 045-12398



Photo # 8469 Location



Photo # 8470 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER A10 well

Location ID: 311651

API # 045-12398



Photo # 8471 Possible wellhead leak/gas bubbling up around wellhead through water in cellar



Photo # 8472 Possible wellhead leak/gas bubbling up around wellhead through water in cellar

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER A10 well

Location ID: 311651

API # 045-12398



Photo # 8473 Possible wellhead leak/gas bubbling up around wellhead through water in cellar



Photo # 8474 Possible wellhead leak/gas bubbling up around wellhead through water in cellar

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER A10 well

Location ID: 311651

API # 045-12398



Photo # 8475 Possible leak/gas bubbling up through water in cellar around bradenhead line



Photo # 8476 Possible leak/gas bubbling up through water in cellar around bradenhead line