

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/28/2024

Submitted Date:

05/29/2024

Document Number:

708903912

FIELD INSPECTION FORM

Loc ID 311651 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 ECMC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635

Findings:
9 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Katz, Aaron		aaron.katz@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285152	WELL	PR	09/01/2023	GW	045-12398	SNYDER A10	PR

General Comment:

[CECMC Inspection Report Summary](#)
 On 05/28/2024 at approximately 12:10 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection on TEP ROCKY MOUNTAIN LLC SNYDER A10 well. Location # 311651 in Garfield County Colorado. API # 045-12398
 Please refer to inspection 708903220 conducted on 03/07/2024, previous corrective action for Mechanical Condition - Possible leaks on SNYDER A10 wellhead & bradenhead line has not been completed & CA date remains of 03/08/2024. Location is within High Priority/Density/Black Bear Habitat areas & multiple Bald Eagle Roost Sites & in close proximity to NSO Habitat area.
 Location is within Rule 411a Surface Water Internal Buffer.
 Location is approximately 400 yards from the Colorado River.
 Location is within close proximity to multiple National Wetlands Inventory areas.
 While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Mechanical Condition - Possible leaks on SNYDER A10 wellhead & bradenhead line with a CA date of 03/08/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
 This is a summary of inspection report
 Limited inspection of the SNYDER A10 wellhead only.
 Any corrective actions from previous inspections that have not been addressed are still applicable.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	# 1		corrective date
Comment:	Well on plunger lift		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Taylor plug located on bradenhead, bradenhead valve is accessible.		
Corrective Action:			Date:
Type: Other	# 2		
Comment:	Mechanical Condition - Possible wellhead leak/gas bubbling up around wellhead through water in cellar & also bubbling up around bradenhead line in cellar. (SNYDER A10 well)		
Corrective Action:	All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition.		Date: 03/08/2024
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 285152 Type: WELL API Number: 045-12398 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Limited inspection of the SNYDER A10 wellhead only.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Equipment for corrective action.	smelserw	05/29/2024
Limited inspection of the SNYDER A10 wellhead only.		
Any corrective actions from previous inspections that have not been addressed are still applicable.		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903913	Inspection 708903912 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6567160
708903914	Inspection 708903912 wellhead leak video 1	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6567161
708903915	Inspection 708903912 wellhead leak video 2	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6567162
708903916	Inspection 708903912 bradenhead leak video	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6567163