

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad
Location ID: 335448



Location Overview: Location is within High Priority/Density Habitat areas. Location is approximately 315 yards from a creek/drainage that contributes to the Colorado River.

Section/Township/Range: 18 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad
Location ID: 335448



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad
Location ID: 335448



Photo # 8667 Failure to maintain chemical BMP/chemical containment full of fluid & not sufficient to contain possible spill



Photo # 8668 Failure to maintain chemical BMP/chemical containment full of fluid & not sufficient to contain possible spill

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad
Location ID: 335448



Photo # 8669 Failure to maintain chemical BMP/chemical containment full of fluid & not sufficient to contain possible spill



Photo # 8670 Failure to maintain chemical BMP/chemical containment full of fluid & not sufficient to contain possible spill

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad
Location ID: 335448



Photo # 8671 Failure to maintain chemical BMP/chemical containment full of fluid & not sufficient to contain possible spill



Photo # 8672 Failure to maintain chemical BMP/chemical containment full of fluid & not sufficient to contain possible spill

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad
Location ID: 335448



Photo # 8673 Failure to maintain chemical BMP/chemical containment 7/8th full of fluid & not sufficient to contain possible spill



Photo # 8674 Edge of pad has started to slough & started to damage berm/BMP (N/NE area of pad behind production units)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad
Location ID: 335448



Photo # 8675 Edge of pad has started to slough & started to damage berm/BMP (N/NE area of pad behind production units)



Photo # 8676 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad
Location ID: 335448



Photo # 8677 Lack of stabilization/compaction



Photo # 8678 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad
Location ID: 335448



Photo # 8679 Lack of stabilization/compaction



Photo # 8680 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad
Location ID: 335448



Photo # 8681 Lack of stabilization/compaction