

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad

Location ID: 335448



Photo # 8640 From entrance to location



Photo # 8641 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad

Location ID: 335448



Photo # 8642 Location

Photo # 8643 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad

Location ID: 335448



Photo # 8644 Location



Photo # 8645 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad

Location ID: 335448



Photo # 8646 Location



Photo # 8647 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad

Location ID: 335448




Photo # 8648 Unmarked deadman



Photo # 8649 Same unmarked deadman from different angle

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad

Location ID: 335448



Photo # 8650 Unmarked deadman



Photo # 8651 Same unmarked deadman from different angle

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad

Location ID: 335448



Photo # 8652 Rupture disc vent line does not comply with CECMC pressure safety device rules



Photo # 8653 Rupture disc vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad

Location ID: 335448



Photo # 8654 Battery sign weathered/faded/cracking/
becoming illegible & does not comply with CECMC rules

Photo # 8655 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad

Location ID: 335448



Photo # 8656 Stained soils & gravel



Photo # 8657 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad

Location ID: 335448



Photo # 8658 Stained soils & gravel



Photo # 8659 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad

Location ID: 335448



Photo # 8660 Stained soils & gravel



Photo # 8661 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad

Location ID: 335448



Photo # 8662 Stained soils & gravel



Photo # 8663 Multiple wellhead signs weathered/fading & cracking & starting to become illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad

Location ID: 335448



Photo # 8664 Multiple wellhead signs weathered/fading & cracking & starting to become illegible



Photo # 8665 Multiple wellhead signs weathered/fading & cracking & starting to become illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 11-19 Pad

Location ID: 335448



Photo # 8666 Location