

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403781007

Date Received:

05/22/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708903649

Inspection Date: 04/25/2024

FIR Submit Date: 04/28/2024

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 323980

Location Name: GIBSON GULCH UNIT-66S91W Number: 30SWSE County: _____

Qtrqr: SWSE Sec: 30 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.493791 Longitude: -107.596111

FACILITY - API Number: 05-045- -00 Facility ID: 323980

Facility Name: GIBSON GULCH UNIT-66S91W Number: 30SWSE

Qtrqr: SWSE Sec: 30 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.493791 Longitude: -107.596111

CORRECTIVE ACTIONS:

1 ☒ CA# 194744

Corrective Action: Comply with CECMC general safety rules & pressure safety device rules

Date: 05/05/2024

Response: CA COMPLETED

Date of Completion: 05/02/2024

Operator Comment: PRV vent line and rupture disc vent line now comply with CECMC pressure safety device and general safety rules. Corrective Action complete.

ECMC Decision: Approved pending re-inspection

ECMC Representative:			
2	✔	CA# 194745	
Corrective Action:	Comply with CECMC Stormwater rules		Date: 05/13/2024
Response:	CA COMPLETED		Date of Completion: 05/02/2024
Operator Comment:	Culvert at entrance of location has been maintained. Corrective Action complete.		
ECMC Decision:	Approved pending re-inspection		
ECMC Representative:			

OPERATOR COMMENT AND SUBMITTAL	
Comment:	CA #194744: PRV vent line and rupture disc vent line now comply with CECMC pressure safety device and general safety rules. Corrective Action complete. CA #194745: Culvert at entrance of location has been maintained. Corrective Action complete.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Jordan Veith	Signed: _____
Title: TEP Representative	Date: 5/22/2024 12:03:37 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403781007	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files