

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2024

Submitted Date:

05/24/2024

Document Number:

708903872**FIELD INSPECTION FORM**Loc ID 311555 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**28 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210778	WELL	PR	09/02/1987	GW	045-06536	MOBIL W-20-32	PR
269557	WELL	PR	01/26/2004	GW	045-09381	PA 542-32	PR
269558	WELL	PR	12/18/2004	GW	045-09382	PA 442-32	PR
269559	WELL	PR	09/25/2003	GW	045-09384	PA 42-32	PR
269560	WELL	PR	02/19/2004	GW	045-09383	PA 342-32	PR

**General Comment:****CECMC Inspection Report Summary**

On 05/23/2024 at approximately 08:55 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC MOBIL W-20-32 Pad.

Location # 311555 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas &amp; in close proximity to Bald Eagle Roost Site.

Location is in close proximity to Rule 411a Surface Water External Buffer.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Housekeeping - Wellhead cellars lack wildlife protection/wildlife hazard/available for entry by wildlife with a CA date of 05/31/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Small amount of staining near 2 wellheads		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Wellhead cellars lack wildlife protection/wildlife hazard/available for entry by wildlife Cellars also lack wildlife egress		
Corrective Action:	Comply with CECMC wildlife rules	Date:	05/31/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Chemical tank - hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	PA 442-32 & W 20-32 wells have Taylor plugs located on bradenheads, bradenhead valves are accessible.  Remaining 3 wells have no form of pressure monitoring equipment located on bradenheads. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:	W 20-32 well not on plunger lift  Remaining 4 wells all on plunger lift		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	STEEL AST		,	
Comment:	Tank damaged - please refer to photo log  Tank equipped with telemetry					

Corrective Action:				Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth					
Comment:					
Corrective Action:				Date:	
<u>Venting:</u>					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	210778	Type:	WELL	API Number:	045-06536	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well not on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	269557	Type:	WELL	API Number:	045-09381	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	269558	Type:	WELL	API Number:	045-09382	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	269559	Type:	WELL	API Number:	045-09384	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	269560	Type:	WELL	API Number:	045-09383	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Berms						
Rip Rap						
Ditches						
		Ditches				
		Tracking Pad				Aggregate/gravel based VTC
		Other				Small amount of rill erosion on lease road
Check Dams						
Sediment Traps						
Gravel						Sparse to none in most areas
		Compaction				Light compaction in some areas
				Material Handling And Spill Prevention		Chemical tank containment
		Gravel				Sparse to none in most sections
Compaction						Light compaction in some areas

Comment: Small amount of rill erosion on section of lease road

Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.

Aggregate/gravel based VTC at intersection of public road & start of lease road. Dimensions & details are as follows approximately 75 ft long, 27 ft wide & varying depths from 1-3 inches, depth insufficient, area does not appear to have been excavated & no class 2 geotextile fabric observed.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
Please refer to Housekeeping for observed compliance issues.	smelserw	05/24/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403803441	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6561607">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6561607</a>
708903873	Inspection 708903872 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6561599">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6561599</a>
708903874	Inspection 708903872 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6561600">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6561600</a>