

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/30/2024

Submitted Date:

05/31/2024

Document Number:

696205842

FIELD INSPECTION FORMLoc ID 416051 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Arthur, Denise		denise.arthur@state.co.us	
,		COGCC.inspections@caerus oilandgas.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416051	LOCATION	CL			-	SGU Frac Pad J25496	RI
418127	PIT	CL			-	SGU FRAC PAD J25 496	RI

General Comment:

On 5/30/2024 Reclamation Specialist Trujillo conducted an inspection at Caerus Piceance LLC's SGU Frac Pad J25496 Location in Garfield County, Colorado.

The following compliance issues were observed during this inspection:

-Final Reclamation

Refer to the "Reclamation" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

Inspected Facilities									
Facility ID:	416051	Type:	LOCATION	API Number:	-	Status:	CL	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	418127	Type:	PIT	API Number:	-	Status:	CL	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use: RANGELAND

Comment:

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING

Comment

Corrective Action Date

1002b. SOIL REMOVAL AND SEGREGATION

Comment

Corrective Action Date

1002c. PROTECTION OF SOILS

Comment

Corrective Action Date

1002E. SURFACE DISTURBANCE MINIMIZATION

Comment

Corrective Action Date

1003a. Waste and Debris removed?

Comment

Corrective Action Date

Unused or unneeded equipment onsite?

Comment

Corrective Action Date

Pit, cellars, rat holes and other bores closed?

Comment

Corrective Action Date

Guy line anchors marked?

Comment

Corrective Action Date

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed **Fail**

Location and associated production facilities reclaimed **Fail** Locations, facilities, roads, recontoured **Fail**

Compaction alleviation **Fail** Dust and erosion control _____

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: [See "COGCC Comments" at the end of this report.](#)

Corrective Action: **Comply with 1004 Rules and conduct final reclamation.** Date **07/01/2024**

Overall Final Reclamation **Fail** Well Release on Active Location ☐ Multi-Well Location ☐

ECMC Comments

Comment	User	Date
<p>Pursuant to Form 2A #400027305, the SGU Frac Pad J25 496 Location (#416051) was permitted as a Frac Pad with a "Special Purpose Pit" (Pit Facility #418127) for completion operations to the SGU B36 496 (#415180) and SGU F25 496 (#415182) pads.</p> <p>Pursuant to Form 4 #40041445, Operator received a variance to operate the pit until 7/8/2014. Operator's reasoning for the extension of the permit was to "allow Encana to operate the pit for an additional 12 months. During this time, Encana will continue to utilize this pit to support completion operations in the Story Gulch area. Once the Divide Road Water Facility (Form 28 currently under review with the COGCC) is operational, the subject pit will be closed and the area will be reclaimed".</p> <p>-All wells on the SGU B36 496 (#415180) and SGU F25 496 (#415182) Locations associated with the permit have been drilled or abandoned; Location no longer necessary for Frac/Completion operations.</p> <p>-Pit was closed via Remediation Project #8534 and Form 4 #400786610 and the Location and Facility has been "Closed".</p> <p>-Form 28 #2232415 for the Divide Water Facility (#432214) was approved 7/21/2014.</p> <p>It was observed in this inspection that the pit has been backfilled, the Gas or Diesel Motors and tank equipment identified in the Form 2A have been removed, and any remaining equipment on the Location appears to have been disconnected and/or no longer necessary for production Operations at the Location. All Locations associated with this Frac Pad identified on the Location's 2A have been constructed and wells drilled, and the Divide Water Facility is operational.</p> <p>Location is subject to 1004 Final Reclamation requirements.</p>	trujilloam	05/31/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696205843	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6569789