

Construction and Stormwater Inspection

Date: 5/24/24

Operator: Crestone Peak Resources Operating LLC -
10633

Location ID: 486500

Inspection Document #: 713900660

Arapahoe County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Lussing Trust 4-64/19-20 North
Location ID: 486500



Photo 1. The photo was taken at the entrance to the well location facing Southwest. The photo illustrates the newly poured concrete entrance skirt.



Photo 2. The photo was taken at the entrance to the well location facing South. The photo illustrates the initial access road used while the concrete entrance sets.

Note - this access road will need reclaimed.

Inspection Photos

Location Name: Lussing Trust 4-64/19-20 North

Location ID: 486500



Photo 3. The photo was taken at the well location facing East. The photo illustrates the access road topsoil has been salvaged to either side and is still in the process of being stabilized.

Photo 4. The photo was taken at the well location facing Northeast. The photo illustrates the disturbance area boundary fencing and topsoil removal in process.

Inspection Photos

Location Name: Lussing Trust 4-64/19-20 North

Location ID: 486500



Photo 5. The photo was taken at the well location facing East. The photo illustrates topsoil removal in process as well as perimeter erosion control.

Photo 6. The photo was taken at the well location facing South. The photo illustrates the topsoil being stockpiled.