

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



When replaced additional information will be required



Oily waste. Stained soil.

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



Oily waste. Covered staining?



Open to wildlife

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



No containment or contents label.



Open to wildlife.

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



Oily waste. Open to wildlife.



Open end tank valve. Stained soil.

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



Debris. Stained soil.



Open end tank valve. Oily waste. Stained soil.

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



Debris. Stained soil.



Oily waste. Open end tank valve

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



Oily waste. Open end tank valve.



Debris

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



Unmarked anchors



Oily waste around wellhead

**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



Location from Northwest corner



Location from Northwest corner



**Antler Energy LLC
Federal-Chamberlin 22-1
Location ID: 312863**



Location from Southeast corner



Location from Northeast corner