

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/31/2024

Submitted Date:

05/31/2024

Document Number:

698706423

FIELD INSPECTION FORMLoc ID 426799 Inspector Name: Serna, Abe On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------------------------------|
| /, Chevron | | rbucogccinspectionreports@c hevron.onmicrosoft.com | All Inspections |
| , | | randy.silver@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 426810 | WELL | PR | 12/01/2023 | OW | 123-34786 | FIVE M E28-67HN | PR |
| 426842 | WELL | PR | 12/01/2023 | OW | 123-34797 | FIVE M E28-69HN | PR |

General Comment:[Wellsite Inspection](#)

LocationOverall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | | Date: | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|----------------------|-------|------------|
| Type | OTHER | | |
| Comment: | Overgrown Vegetation | | |
| Corrective Action: | Comply with rule 606 | Date: | 06/14/2024 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Panels | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|--------------------|-----|-------|-----------------|
| Type: Plunger Lift | # 2 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|---|--------|----------------------------|------|------------------------|-----------|------------------|----|---------------|----|
| Facility ID: | 426810 | Type: | WELL | API Number: | 123-34786 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | PR | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: | | 02/20/2024 | | Annual Brhd Completed? | | Yes | | | |
| Last Brhd Test Results | | Initial Surf Csg Pressure: | | 10 | | Fluid Type: | | | |
| | | End Surf Csg Pressure: | | 0 | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 426842 | Type: | WELL | API Number: | 123-34797 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | PR | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: | | 07/25/2023 | | Annual Brhd Completed? | | Yes | | | |
| Last Brhd Test Results | | Initial Surf Csg Pressure: | | 0 | | Fluid Type: NONE | | | |
| | | End Surf Csg Pressure: | | 0 | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| ECMC Comments | | | | | | | | | |
| Comment | | | | | | User | | Date | |
| ECMC Inspection Report Summary On 5-31-24 at 9:30 am, I, Inspector Abe Serna, conducted an on-site inspection. Location: FIVE M E28-69HN Operator: Noble Energy API#: 123-34797 County: Weld County While there, I observed overgrown vegetation inside the wellhead area During this inspection the following possible compliance issues were observed: Rule 606 See attached photo #. 2 Corrective Action Date: 6-14-24 Weather conditions: Overcast A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report. Any corrective actions from previous inspections that have not been addressed are still applicable | | | | | | sernaa | | 05/31/2024 | |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------|---|
| 403809522 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6569438 |
| 698706424 | Photo | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6569433 |