

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/28/2024

Submitted Date:

05/31/2024

Document Number:

700300736**FIELD INSPECTION FORM**Loc ID 325501 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
, General		sjninspections@ikavenergy.com	All SW Inspections
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214901	WELL	PR	03/22/1988	CBM	067-06505	SHOEMAKER 01-34 1	PR

General Comment:

Inspection in response to complaint from local governe~~m~~nt Form 18 doc# 403801695 alledging that operator failed to notify ECMC of incidnet which required emergency response and actions.

[See complaint section of report](#)

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Good Housekeeping:

Type	OTHER		
Comment:	Observed oxide staining on gravel near separator, appears releases may have occurred from ~1/4 stainless tubing from separator (see slides 8 and 9)		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	sound walls enclosing mobile compressor		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Compressor	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Plastic riser behind separator (see slide 10) appears to be no longer in use, related to equipment that has been removed.		
Corrective Action:		Date:	

Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:			
Corrective Action:			Date:
Type: Dehydrator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLs	STEEL AST		37.255964,-107.728797	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	214901	Type:	WELL	API Number:	067-06505	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Complaint									
Comment:		Inspection in response to complaint doc #403801695 which is related to 1/15/24 incident in which emergency responders were dispatched and according to fire department report submitted as attachment with complaint required residents to shelter in place and the well to be shiut in remotely due to gas measurments made by first responders. Intial report to ECMC was required within 6 hours of event. Complainant (La Plata County) alledges that state and local government was not notified. A review of ECMC database and well file did not find any Form 22 related to well or incident as required by such an incident by Rule 603.g There was also a incident on 1/17/24 which did not require actions by responders or operator							
Corrective Action:		Submit From 22 detailing cause and resolution of conditions that required emergency response and related actions on 1/15/24 per Rule 602.g and 602.h Submit Grade 1 gas leak via Forms 19 and 44 if applicable per Rule 613				Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Pass					
Ditches	Pass					
Compaction	Pass	Compaction				
Gravel	Pass	Gravel				

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Optical Gas Imaging SurveySurvey Type: ComplaintCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Gusts Speed: 0-10 (mph) Direction From: SW Weather: Clear Temperature: (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
~1	PM	~1:30	PM

Equipment
Flowline
Separation Equipment
Wellhead(s)
Water Tank(s)
Other

Comment: No FLIR detectable gas (high sensitivity) detected other than associated with exhaust from compressor rising out from open top of sound abatement structureCorrective
Action:

Date:

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403809626	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6569573
700300738	INSPECTION PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6569570
700300739	FD REPORT (VAPOR)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6569571
700300740	FD REPORT (GAS LEAK)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6569572