

# Inspection Photos

API: 017-06625

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 5/30/2024

County: Cheyenne



## Inspection Photos



**Photo 1.** Facing east along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and shall not drive outside of the access road boundary.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06625 | Date: 5/30/2024

## Inspection Photos



**Photo 2.** Facing east along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and shall not drive outside of the access road boundary.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06625 | Date: 5/30/2024

## Inspection Photos



**Photo 3.** Facing northeast toward the wellsite. There is impacted soils from the previous spill that were not cleaned up.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06625 | Date: 5/30/2024

## Inspection Photos



**Photo 4.** It appears there was sand spread on top of the spill which was not cleaned up per the rules.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06625 | Date: 5/30/2024

Inspection Photos



**Photo 5.** The pumpjack engine is still leaking oil and there



## Inspection Photos



**Photo 6.** It appears there was sand spread on top of the spill which was not cleaned up per the rules.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos



**Photo 7.** Facing west toward the location. There is water pooling at the east side of the location..

