

# Inspection Photos

API: 017-06636

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 5/30/2024

County: Cheyenne



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing south along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and vehicles shall not drive outside of the access road boundary. Previous corrective action was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06636 | Date: 5/30/2024



## Inspection Photos



**Photo 2.** Facing south along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and vehicles shall not drive outside of the access road boundary. Previous corrective action was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06636 | Date: 5/30/2024




## Inspection Photos



**Photo 3.** Facing west along the road toward the wellsite. There has been gravel spread along the area where erosion channel was previously observed.



## Inspection Photos



**Photo 4.** Facing west toward the wellsite..



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API:017-06636 | Date: 5/30/2024



## Inspection Photos



**Photo 5.** There are oily rags in this are that must be disposed.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 6.** Facing toward the wellhead. The barrel is not properly set in the containment and there is no netting on the secondary containment..



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 7.** Facing toward the electric utility just south of the well. The electric wire is on the surface and not protected which is a safety concern. The electric breaker is disconnected from the electric line.

