

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403817248

Date Received:

06/07/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Shorty, Priscilla

505-324-5188

pshorty@hilcorp.com

.General

FarmingtonRegulatoryTechs@hilcorp.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 714000781

Inspection Date: 05/21/2024

FIR Submit Date: 05/23/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

### LOCATION - Location ID: 326297

Location Name: HUBER-LEWIS-N35N8W Number: 33SWSE County: \_\_\_\_\_

Qtrqtr: SWSE Sec: 33 Twp: 35N Range: 8W Meridian: N

Latitude: 37.253786 Longitude: -107.748046

### FACILITY - API Number: 05-067-00 Facility ID: 326297

Facility Name: HUBER-LEWIS-N35N8W Number: 33SWSE

Qtrqtr: SWSE Sec: 33 Twp: 35N Range: 8W Meridian: N

Latitude: 37.253786 Longitude: -107.748046

### CORRECTIVE ACTIONS:

1 ☒ CA# 195387

Corrective Action: Comply with rule 606. Remove and properly store unused equipment.

Date: 06/07/2024

Response: CA COMPLETED

Date of Completion: 06/06/2024

Operator  
Comment:

Piping has been removed from location. See attached photos.

ECMC Decision: Approved pending re-inspection

ECMC Representative:	Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.		
----------------------	--	--	--

  

2
✔
CA# 195388

Corrective Action: Maintain equipment and clean up impacted material and dispose per Rule 906 and 1002.

Response: CA COMPLETED

Operator Comment: Maintenance has been completed and impacted soil has been removed and disposed of. See attached photos

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

Date: 05/28/2024

Date of Completion: 06/06/2024

  

3
✔
CA# 195389

Corrective Action: Comply with rule 1002 Install or repair required BMPs.

Response: CA COMPLETED

Operator Comment: Storm water diversion has been stabilized with aggregate to minimize erosion in channel.

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

Date: 05/30/2024

Date of Completion: 06/06/2024

  

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed:

Title: OperationsRegulatory Tech

Date: 6/7/2024 10:06:40 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403817248	FIR RESOLUTION SUBMITTED
403817256	Huber-Lewis 2-33 Resolved Photos

Total Attach: 2 Files