

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/05/2024

Submitted Date:

06/07/2024

Document Number:

710500310**FIELD INSPECTION FORM**Loc ID 426430 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426435	WELL	PR	05/01/2012	CBM	071-09898	Champion 44-9 R	EI

General Comment:

This is an Environmental Inspection for the Champion 44-9 R well location located in Las Animas County, Co

LocationOverall Good: ☐**Signs/Marker:**

Type OTHER

Comment: [WDID Sticker not present](#)[Update sign to comply with Rule 605.g.](#)

Corrective Action:

Date:

Emergency Contact Number:Comment: [Well Placard on Meter House](#)

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type Area Volume

In Containment: No

Comment: [Packing leak observed at the time of inspection. Contacted Ed Romero, Production Foreman on 6/5/2024 @ 11.33 a.m. Lease operator dispatched to repair. ENR contacted ECMC @ 2:09 p.m. indicating packing leak repaired.](#)

[Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.](#)

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PLASTIC AST		,

Comment: [Produced water tank near separator is broken and is missing cap](#)Corrective Action: [Inspect, maintain and repair tanks to comply with rule 609.b.](#)Date: 07/09/2024**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID:	426435	Type:	WELL	API Number:	071-09898	Status:	PR	Insp. Status:	EI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500311	Inspection 710500310, location photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6578587