

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2024

Submitted Date:

06/07/2024

Document Number:

710500319

**FIELD INSPECTION FORM**

Loc ID 334200 Inspector Name: Sanchez, Chris On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1875 LAWRENCE ST STE 1150  
City: DENVER State: CO Zip: 80202

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258523	WELL	PR	12/08/2001	CBM	071-07098	SILVERLAND 31-22	EG
261321	PIT	AC			-	SILVERLAND 31-22	EI
288806	WELL	PR	04/03/2007	CBM	071-09156	SILVERLAND 31-22 TR	EG
301239	PIT	AC			-	SILVERLAND 31-22 TR	EI

**General Comment:**

This is an Environmental Inspection for the Silverland 31-22 and Silverland 31-22 TR well location located in Las Animas County, Co

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 258523 Type: WELL API Number: 071-07098 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 261321 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 288806 Type: WELL API Number: 071-09156 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301239 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Drill Cuttings	Other	Inadequate		
Comment	There is a pile of grey material located on the southwest corner of the well pad. The material appears to be E&P Waste excavated from the pit. In addition, the same material is located on the working surface of the well pad.			
Corrective Action	E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 905. Contact ECMC EPS staff.			Date: 06/10/2024

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 261321 Lat: 37.249321 Long: -104.764807

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Livestock Fencing Condition: Inadequate

Comment: Pit fencing needs repaired to prevent livestock access

Corrective Action Maintain fencing per Rule 603.h.

Date: 07/09/2024

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Type: Produced Water Lined: YES Pit ID: 301239 Lat: 37.249340 Long: -104.764500

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: PVC Liner Condition: \_\_\_\_\_

Comment: Pit is in the process for Closure per Remediation project # 33165. There are pieces of pit liner in the anchor trench that will need to be removed.

Comment: Dispose of Pit Liner in accordance with Rule 911.c.(3)

Comment: Operator shall notify area EPS when interim reclamation has been completed.

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

<b>Comment:</b>			<b>Date:</b>
<b>Corrective Action</b>			
<b>Anchor Trench Present:</b>	<b>Oil Accumulation:</b>	<b>2+ feet Freeboard:</b>	
<b>Comment:</b>			<b>Date:</b>
<b>Corrective Action</b>			
<b>Permit:</b>	<b>Facility ID</b>	<b>Permit Num</b>	<b>Expiration Date</b>
	301239	1942044	
	261321	852052	
	301239	1942044	
<b>Monitoring:</b>	<b>Monitoring Type</b>	<b>Comment</b>	
	Chain		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500323	Inspection 710500319, Location Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6578591">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6578591</a>