

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9937 From entrance to location

Photo # 9938 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9939 Location



Photo # 9940 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9941 Location

Photo # 9942 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9943 Location



Photo # 9944 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9945 Debris

Photo # 9946 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9947 Debris



Photo # 9948 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9949 Barbed wire fence needs maintenance/wildlife hazard



Photo # 9950 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9951 Barbed wire fence needs maintenance/wildlife hazard



Photo # 9952 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9953 Barbed wire fence needs maintenance/wildlife hazard



Photo # 9954 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9955 Holes in liner/liner needs maintenance



Photo # 9956 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9957 Holes in liner/liner needs maintenance



Photo # 9958 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9959 Holes in liner/liner needs maintenance



Photo # 9960 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9961 Holes in liner/liner needs maintenance



Photo # 9962 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9963 Holes in liner/liner needs maintenance



Photo # 9964 Holes in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9965 Holes in liner/liner needs maintenance




Photo # 9966 Holes in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9967 Hole in liner/liner needs maintenance



Photo # 9968 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9969 Hole in liner/liner needs maintenance



Photo # 9970 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9971 Holes in liner/liner needs maintenance



Photo # 9972 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC GRAHAM 32-12 (L32) Pad

Location #: 334830



Photo # 9973 Hole in liner/liner needs maintenance