

Inspection Photos

May 30th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 325300

Inspection Document #: 714000812

La Plata County, CO

Township: NENE 1 32N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Squires 1, 4
Location ID: 325300



5/30/24
+37.051407,-107.554315
220° SW



Photo 1. View of the well disturbance taken from the access road facing center.

Inspection Photos
Location Name: Squires 1, 4
Location ID: 325300



Photo 2. View of the diversion and evidence of sediment transport/deposition. Reseeding appears unsuccessful as interim reclamation areas to the south are dominated by weedy vegetation.

Inspection Photos
Location Name: Squires 1, 4
Location ID: 325300



Photo 3. Sever gully erosion observed forming throughout the southern portions of the interim reclamation area, additional stabilization is needed.

Inspection Photos
Location Name: Squires 1, 4
Location ID: 325300



Photo 4. Additional photos of gully erosion and evidence of sediment transport off of location in the southern interim reclamation area.

Inspection Photos
Location Name: Squires 1, 4
Location ID: 325300



Inspection Photos
Location Name: Squires 1, 4
Location ID: 325300

5/30/24
+37.034812,-107.627807
359° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Reference are comprised of sage brush and squirrel tail.

API #: 067-06118, 09762