

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/23/2024

Submitted Date:

06/04/2024

Document Number:

709100301

**FIELD INSPECTION FORM**

Loc ID 312223 Inspector Name: Heibel, Krystal On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 17180  
Name of Operator: CITATION OIL & GAS CORP  
Address: 14077 CUTTEN RD  
City: HOUSTON State: TX Zip: 77069

**Findings:**

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Harris, Debra		dharris@cogc.com	
WARD, SHARON		sward@cogc.com	
Krystal Heibel		krystal.heibel@state.co.us	
Rogers, Bob		brogers@cogc.com	
Kym Shure		kym.schure@state.co.us	
Kennedy, Herschel		hkennedy@cogc.com	
Kyle Waggoner		kyle.waggoner@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219676	WELL	PR	06/01/2020	OW	075-06675	ARTHUR SINDT 8	EI

**General Comment:**

On May 23, 2024, ECMC Environmental Unit Staff Krystal Heibel inspected the ARTHUR SINDT-610N52W/31NESW location (Location ID: 312223).

The location is in close proximity to Beall Creek.

Any corrective actions from previous forms that have not been addressed are still applicable. Photos are attached to document site conditions at the time of the inspection.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Tumbleweeds present in fence		
Corrective Action:	Comply with Rule 606	Date:	06/11/2024

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
	WELLHEAD		
Comment:	Stained soil located next to wellhead and outside of fenced area. See photo documentation.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. In accordance with 913.d. (1) Operator will investigate impacts to soil, groundwater, and surface water as soon as the impacts are discovered. Additionally, Operator shall provide an explanation of how the volume of liquids spilled was calculated on a Form 19 Supplemental Report and comply with Rule 912 series rules for Spills and Releases.		Date: 06/06/2024

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No		
Comment:	<input type="text"/>	
Corrective Action:		Date:

**Flaring:**

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 219676 Type: WELL API Number: 075-06675 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403813762	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6573824">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6573824</a>
709100302	photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6573809">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6573809</a>