

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/23/2024

Submitted Date:

06/04/2024

Document Number:

709100312

**FIELD INSPECTION FORM**

Loc ID: 312218 Inspector Name: Heibel, Krystal On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 17180  
Name of Operator: CITATION OIL & GAS CORP  
Address: 14077 CUTTEN RD  
City: HOUSTON State: TX Zip: 77069

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kym Shure		kym.schure@state.co.us	
Kyle Waggoner		kyle.waggoner@state.co.us	
Krystal Heibel		krystal.heibel@state.co.us	
Kennedy, Herschel		hkennedy@cogc.com	
Harris, Debra		dharris@cogc.com	
Rogers, Bob		brogers@cogc.com	
WARD, SHARON		sward@cogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219649	WELL	PR	02/01/2023	OW	075-06625	W E DICKINSON 1	EI

**General Comment:**

On May 23, 2024, ECMC Environmental Unit Staff Krystal Heibel inspected the W E DICKINSON-69N52W/6NESW location (Location ID: 312218).

The location is in close proximity to Beall Creek.

Any corrective actions from previous forms that have not been addressed are still applicable. Photos are attached to document site conditions at the time of the inspection.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		
Lube Oil	WELLHEAD			
Comment:	At the time of this inspection, Staff observed a hydrocarbon release/spill at the polish rod and on nearby soil. Staff was unable to determine the approximate volume. See photo documentation.			
Corrective Action:	Immediately remove oily waste. Removal of impacted soils in excess of Table 915-1 or other remedial activities must be initiated to fully define the vertical and horizontal extent of impacts at the remediation site. Rule 912.a(5) requires that any spills or releases that do not meet the reporting requirements of Rule 912.b. Operators will document and cleanup efforts and provide documentation of the cleanup to the director upon request. Perform cleanup of this area and provide documentation of the activities by means of an update to the form 19 for this site.			Date: <u>06/06/2024</u>

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	

**Flaring:**

Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 219649 Type: WELL API Number: 075-06625 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403813776	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6573836">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6573836</a>
709100313	photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6573814">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6573814</a>