

Inspection Photos

API: 071-06970

Operator: WAPITI OPERATING LLC

Inspection Date: 6/10/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast along the access road. The culvert has filled in with sediment and needs to be cleaned out.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06970 | Date: 6/10/2024

Inspection Photos



Photo 2. Facing northeast along the road. There are noxious weeds that need to be controlled. Houndstongue



Inspection Photos



Photo 3. Facing east toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Facing northwest the cut slope. There are erosion channels that need to be repaired. The wattles at red arrow has failed.



Inspection Photos



Photo 5. The top of the cut slope need to be stabilized and may require a run-on ditch or other BMP's.



Inspection Photos



Photo 6. Facing northwest along the cut slope. There are erosion channels that must be repaired and stabilized.



Inspection Photos



Photo 7. There are black polylines at the fill slope that must removed.



Inspection Photos



Photo 8. Facing northeast toward the flowline.



Inspection Photos



Photo 9. Facing northeast along the flowline. There are numerous noxious weeds that must be controlled. Observed Canada thistle, Houndstongue, Mullein.



Inspection Photos



Photo 10. There are numerous noxious weeds that must be controlled. Observed Canada thistle, Houndstongue, Mullein.



Inspection Photos



Photo 11. Facing northeast along the flowline near the offsite tank in the canyon. There are numerous noxious weeds that must be controlled.

