

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/10/2024

Submitted Date:

06/11/2024

Document Number:

713601099**FIELD INSPECTION FORM**Loc ID 307697 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10351Name of Operator: WAPITI OPERATING LLCAddress: 1251 LUMPKIN RDCity: HOUSTON State: TX Zip: 77043**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mattorano, Michael	575-445-6704/505-652-0416	mmattorano@wapitienergy.com	
Madison, Randy	575-445-6706/575-420-1120	rmadison@wapitienergy.com	
Beardslee, Tom		tom.beardslee@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89235	WELL	PR	09/15/1999	CBM	071-06815	VPR C 4	RI

**General Comment:**This is an inspection at the VPR C #4 wellsite.

Location					
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					
Date: <input type="text"/>					
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:					
Type: Flow Line		# 1			corrective date
Comment:		There was gas venting out of the flowline along the access road. Operator was immediately notified. There was no signage and the gas was vented directly at the road way which is a safety concern. Inspector did not drive past the gas line and no other recent vehicle tracks were seen along the road which indicates venting had been going on for more than 8 consecutive hours.			
Corrective Action:		Comply with Rule 903.d.(2) Immediately cease venting. Submit form 4 to report gas venting.			Date: 06/13/2024
Venting:					
Yes/No					
Comment:					
Corrective Action:		Date:			
Flaring:					
Type					
Comment:					
Corrective Action:		Date:			

Inspected Facilities

Facility ID: 89235    Type: WELL    API Number: 071-06815    Status: PR    Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601100	Inspection Photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582180">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582180</a>
713601101	Video	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582181">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582181</a>