

Inspection Photos
Location Name: Wardell H 18-16Jl
Location ID: 331228



Photo 1: Wellhead Sign

Photo 2: TA Wellhead

Inspection Photos
Location Name: Wardell H 18-16JI
Location ID: 331228



Photo 3: Location from entrance

Photo 4: Tank Battery Sign, Operator not legible

Inspection Photos
Location Name: Wardell H 18-16J
Location ID: 331228



Photo 5: Debris

Photo 6: Debris

Inspection Photos
Location Name: Wardell H 18-16JI
Location ID: 331228



Inspection Photos
Location Name: Wardell H 18-16JI
Location ID: 331228




Photo 7: Debris

Photo 8: Debris

Inspection Photos
Location Name: Wardell H 18-16JI
Location ID: 331228



Energy & Carbon Management Commission
40.22215, -104.70029, 1487.7m, 37°
Jun 11, 2024 12:16:50



Energy & Carbon Management Commission
40.22214, -104.7003, 1487.8m, 319°
Jun 11, 2024 12:16:54

Photo 9: Debirs

Photo 9: Deirbs

Inspection Photos
Location Name: Wardell H 18-16JI
Location ID: 331228



Energy & Carbon Management Commission
40.22215, -104.70052, 1490.7m, 44°
Jun 11, 2024 12:17:15

Photo 10: Debris