

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/11/2024

Submitted Date:

06/11/2024

Document Number:

714201126

FIELD INSPECTION FORM
 Loc ID 302872 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num:
Operator Information:

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

33 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159570	WELL	PR	01/18/2016	OW	123-40945	CHEESE 37N-28HZ	PR
159571	WELL	PR	01/26/2016	OW	123-40946	CHEESE STATE 26N-21HZ	PR
159572	WELL	PR	04/01/2019	OW	123-40947	CHEESE STATE 26C-21HZ	PR
159573	WELL	PR	07/01/2018	OW	123-40948	CHEESE STATE 1N-21HZ	PR
159574	WELL	PR	12/31/2015	OW	123-40949	CREAM STATE 28C-21HZ	PR
159575	WELL	PR	01/14/2016	OW	123-40950	CHEESE 16N-28HZ	PR
159576	WELL	SI	02/01/2023	OW	123-40951	CREAM 15N-A28HZ	SI
159580	WELL	PR	01/18/2016	OW	123-40955	CHEESE STATE 27N-21HZ	PR
159581	WELL	PR	01/26/2016	OW	123-40956	CHEESE 38N-28HZ	PR
159582	WELL	PR	01/18/2016	OW	123-40957	CHEESE 38C-28HZ	PR
159583	WELL	PR	12/29/2015	OW	123-40958	CREAM STATE 2N-21HZ	PR
159584	WELL	PR	12/28/2015	OW	123-40959	CREAM 15C-28HZ	PR
159585	WELL	PR	01/18/2016	OW	123-40960	CREAM 36N-28HZ	PR
159587	WELL	PR	06/01/2021	OW	123-40962	CREAM STATE 28N-21HZ	PR
159588	WELL	PR	12/31/2015	OW	123-40963	CREAM STATE 2C-21HZ	PR
159589	WELL	PR	12/25/2015	OW	123-40964	CREAM 37N-28HZ	PR
159590	WELL	PR	11/01/2018	OW	123-40965	CREAM 15N-B28HZ	PR
301326	WELL	SI	07/01/2021	OW	123-29959	MOSER H 28-27	TA

General Comment:

THIS IS A WELLHEAD/BATTERY INSPECTION.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris at some wellheads. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	06/25/2024

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 18		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities										
Facility ID:	159570	Type:	WELL	API Number:	123-40945	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	PR; it appears the valves are in an open position.									
Corrective Action:									Date:	
BradenHead										
Date of Last Brhd Test:	02/16/2023		Annual Brhd Completed?		No					
Last Brhd Test Results	Initial Surf Csg Pressure:		0		Fluid Type: None					
	End Surf Csg Pressure:		--							
Comment:	SUBMIT REPORTS									
Corrective Action:									Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	159571	Type:	WELL	API Number:	123-40946	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	PR; it appears the valves are in an open position.									
Corrective Action:									Date:	
BradenHead										
Date of Last Brhd Test:	02/15/2023		Annual Brhd Completed?		No					
Last Brhd Test Results	Initial Surf Csg Pressure:		1		Fluid Type: None					
	End Surf Csg Pressure:		--							
Comment:	SUBMIT REPORTS									
Corrective Action:									Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	159572	Type:	WELL	API Number:	123-40947	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	PR; it appears the valves are in an open position.									
Corrective Action:									Date:	
BradenHead										
Date of Last Brhd Test:	12/19/2023		Annual Brhd Completed?		Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:		1		Fluid Type: NONE					
	End Surf Csg Pressure:		0							
Comment:										
Corrective Action:									Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	159573	Type:	WELL	API Number:	123-40948	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	PR; it appears the valves are in an open position.									
Corrective Action:									Date:	

BradenHead

Date of Last Brhd Test: 02/16/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159574 Type: WELL API Number: 123-40949 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears the valves are in an open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/18/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159575 Type: WELL API Number: 123-40950 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears the valves are in an open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/16/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159576 Type: WELL API Number: 123-40951 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI; it appears the valves are in a closed position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/18/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159580 Type: WELL API Number: 123-40955 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears the valves are in an open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/16/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159581 Type: WELL API Number: 123-40956 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears the valves are in an open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/16/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 7 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159582 Type: WELL API Number: 123-40957 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears the valves are in an open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/15/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 12 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159583 Type: WELL API Number: 123-40958 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears the valves are in an open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/12/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 7 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159584 Type: WELL API Number: 123-40959 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears the valves are in an open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/17/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 21 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159585 Type: WELL API Number: 123-40960 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears the valves are in an open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/18/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159587 Type: WELL API Number: 123-40962 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears the valves are in an open position.

Corrective Action: Date: **BradenHead**

Date of Last Brhd Test: 04/18/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 15 Fluid Type: None

End Surf Csg Pressure: --

Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159588 Type: WELL API Number: 123-40963 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears the valves are in an open position.

Corrective Action: Date: **BradenHead**

Date of Last Brhd Test: 04/12/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159589 Type: WELL API Number: 123-40964 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears the valves are in an open position.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 02/17/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 8 Fluid Type: None

End Surf Csg Pressure: --

Comment: SUBMIT REPORT

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 159590 Type: WELL API Number: 123-40965 Status: PR Insp. Status: PR

Producing Well

Comment: PR; it appears the valves are in an open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/12/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301326 Type: WELL API Number: 123-29959 Status: SI Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder:

Comment: TA; Form 6A in well file.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/20/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 16 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>WEATHER CONDITIONS: sunny, dry ground.</p> <p>On Tuesday, June 11, 2024 at approximately 1330, I, Inspector Brittani Santistevan, conducted an on-site inspection at CREAM 15N-B28HZ (Kerr McGee Oil & Gas Onshore), at location ID: 302872 in WELD COUNTY, Colorado.</p> <p>While there, I observed mostly producing wellheads.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. It appears to be debris on multiple areas of location. Comply with Rule 606. (Corrective Action Date: June 25, 2024) See attached photo #3-6.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	06/11/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714201127	Photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6582963