

Inspection Photos

Loc: 412161

Operator: WAPITI OPERATING LLC

Inspection Date: 6/10/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. There was a riser observed along the flowline that was venting gas.



Inspection Photos



Photo 2. This culvert is not covered along the flowline. The lid needs to be kept on to prevent wildlife entry..



Inspection Photos



Photo 3. Facing northwest along the flowline where disturbance had occurred. The vegetation is establishing and stabilizing soils..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:412161 | Date: 6/10/2024

Inspection Photos



Photo 4. Facing south along the flowline where disturbance had occurred. The vegetation is establishing and stabilizing soils..



Inspection Photos



Photo 5. Facing north along the access road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:412161 | Date: 6/10/2024

Inspection Photos



Photo 6. Facing southwest toward the compressor station.

