

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Jun 10, 2024 at 1:14:30 PM
CO



Jun 10, 2024 at 1:23:17 PM

Photo # 211 From entrance to location

Photo # 212 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Jun 10, 2024 at 1:23:35 PM



Jun 10, 2024 at 1:19:59 PM

Photo # 213 Location

Photo # 214 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 215 Location



Photo # 216 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Jun 10, 2024 at 1:15:34 PM
CO

Photo # 217 Location



Jun 10, 2024 at 1:29:26 PM

Photo # 218 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 219 Wellhead sign weathered & cracking/sign is becoming illegible & does not comply with CECMC rules



Photo # 220 Wellhead sign weathered & cracking/sign is becoming illegible & does not comply with CECMC rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 221 Wellhead sign weathered & cracking/sign is becoming illegible & does not comply with CECMC rules



Photo # 222 Wellhead sign weathered & cracking/sign is becoming illegible & does not comply with CECMC rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 223 Wellhead sign weathered & cracking/sign is becoming illegible & does not comply with CECMC rules



Photo # 224 Wellhead sign weathered & cracking/sign is becoming illegible & does not comply with CECMC rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 225 Small amount of damage near top of secondary containment liner



Photo # 226 Small amount of damage near top of secondary containment liner

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOLL RWF 13-31 Pad

Location ID: 417582



Photo # 227 Stored trailers on location in the interim area

